

RE-ENTRY GUIDE

PRODUCT 30-050


The **TechWest Re-Entry Guide** is used to allow safe entry into the packer, or production string of wireline tools.

It is always run as the bottom piece of the string.

The Re-Entry Guide is available in all common tubing sizes and connections.

SPECIFICATIONS

30-050 SPECIFICATIONS						
Size		Product Number	Max OD		Min ID	
in	mm		in	mm	in	mm
2 3/8	60.3	30-050-0200	3.063	77.800	1.995	50.673
2 7/8	73.00	30-050-0250	3.668	93.167	2.441	62.001
3 1/2	88.9	30-050-0350	4.500	114.300	2.992	75.997
4 1/2	114.3	30-050-0450	5.563	141.300	3.958	100.533



DEHYDRATION NIPPLE

PRODUCT 30-028

The **TechWest Dehydration Nipple** may be used in a production string where the injection of chemicals may be necessary to dissolve solids or other injection requirements.

SPECIFICATIONS

30-028 SPECIFICATIONS								
Size		Product Number	Body OD		Max OD		Min ID	
in	mm		in	mm	in	mm	in	mm
2 3/8	60.3	30-028-0200	3.059	77.7	3.681	93.5	1.933	49.1
2 7/8	73.0	30-028-0250	3.669	93.2	4.311	109.5	2.472	62.8

